# **Understanding the Japanese Auction Sheet**

### **Auction Grade- Exterior**

GRADE	DESCRIPTION	GRADE	DESCRIPTION
S	New	1	Engine swap or has been underwater
5	Same as New	*	Non-running car, needs a forklift to be moved. But also mentioned for any motorbike or machinery
4.5	Excellent grade with almost no issue	R or O	Accident history repaired. Repaired parts are mostly informed on auction sheet
4	Great grade with minor issues only	RA	Minor accident repaired (core support or back panel only)
3.5	Good grade with some issues that may need repair	RB	Heavy repair (till inner panel or floor)
3	Average grade with issues to fix	RC	Pillar or frame has been changed/repaired
2	Bad grade	R2	Accident history and mostly rust or corrosion issue

### **Auction Grade Interior**

GRADE	DESCRIPTION
A	Very Clean like a bland new
В	Very Clean
С	Average Level
	-Some dirt but would be B if it is cleaned.
4.5	-Few Burns, breaks, cuts
	-Dirt that cannot be cleaned
E	-Big Crack on the dashboard, need to be replaced;
	Dirt (Interior, Seats), break

## **Vehicle Options**

OPTIONS	DESCRIPTION	TRANSMISSION	DESCRIPTION
SR	Sunroof	Manual	F5, F6, MT, 5MT, 6MT
AW	Alloy Wheel	Auto	AT, FA, FAT, CVT
PS	Power Steering		
PW	Power Window		
カワ or 革	Leather Seats		
TV	TV		
ナビ	Navigation System		
エアB	Airbag		

## **Detail Condition of the inspection sign**

Symbol	Description	Symbol	Description	
A1	Small Scratch	P	Paint marked	
A2	Scratch	Н	Paint faded	
A3	Big Scratch	X	Need to be replaced	
E1	Few Dimples	XX	Replaced	
E2	Several Dimples	B1	Small dent with scratch (size like a thumb)	
E3	Many Dimples	B2	Dent with scratch (size like flat of the hand)	
U1	Small Dent	В3	Big Dent with scratch (size like elbow)	
U2	Dent	Y1	Small Hole or Crack	
W1	Repair Mark/Wave (hardly detectable)	Y2	Hole or Crack	
W2	Repair Mark/Wave	Y3	Big Hole or Crack	
W3	Obvious Repair Mark/Wave (needs to be repainted)	X1	Small Crack on Windshield (approximately 1cm)	
S1	Rust	R	Repaired Crack on Windshield	
S2	Heavy Rust	RX	Repaired Crack on Windshield (needs to be replaced)	
C1	Corrosion	X	Crack on Windshield (needs to be replaced)	
C2	Heavy Corrosion	G	Stone chip in glass	

## Year comparison

S61	S62	S63	S64/H1	H2	Н3	H4	H5	Н6	H7
1986	1987	1988	1989	1990	1991	1992	1993	1994	1995
H8	H9	H10	H11	H12	H13	H14	H15	H16	H17
1996	1997	1998	1999	2000	2001	2002	2003	2004	2005
H18	H19	H20	H21	H22	H23	H24	H25	H26	H27
2006	2007	2008	2009	2010	2011	2012	2013	2014	2015
H28	H29	H30	R1	R2	R3	R4			
2016	2017	2018	2019	2020	2021	2022			

### 1. BID result

BIDDING OUTCOMES	STATUS
You purchase a car matching your budget or	Bought
close to it.	
Car purchased by someone before you in the	Sold
auction.	
The bids do not reach the reserve price set by	Passed
sellers.	
A passed vehicle sold after negotiation on price.	Sold In Negotiation
A vehicle removed from auction by the seller	Removed
during the process.	